



MODEL 3002, 3003*, 3006* COMPETITOR® PLUS™ (2-lobe)

*current models with 7/8" drive shaft diameter (formerly 3/4")

*Model 3003 revised to 7/8" drive shaft DEC 2001 beginning with S/N 80531

*Model 3006 revised to 7/8" drive shaft NOV 2001 beginning with S/N 80052

(All 3002 models were manufactured with 7/8" drive shaft)

The following list are recommended spare parts for a normal overhaul.
 This list includes all bearings, seals, and miscellaneous locks and screws
 that are not normally reusable after disassembly.

Prices quoted are Ex Works, Springfield, MO USA. Minimum order \$50.

REPAIR KIT 3300638C

<u>Item Number</u>	<u>Description</u>	<u>Part Number</u>	<u>Quantity</u>
11	Roller Bearing	28680	1
12	Ball Bearing	8498	1
13	Ball Bearing	30238-5205	2
22	Retainer	3300538A	2
23	Lip Seal	3300548B	1
24	Lip Seal	3300558B	4
29	Cap Screw	90293-100	2
30	Timing Shim	8550	2
30	Timing Shim	8533	6
30	Timing Shim	8532	2
31	Gear Key	3300318B	2

The following part is listed for reference only and is not a part of the repair kit:

8	Gear Assembly	3300098B	1
---	---------------	----------	---