



Tuthill Vacuum & Blower Systems  
4840 West Kearney Street  
Springfield, Missouri USA 65803-8702  
o 417.865.8715 800.825.6937 f 417.865.2950  
[www.tuthill.com](http://www.tuthill.com)

## **STANDARD BLOWER MODEL 9000-17/46/19/86**

The following list of parts, headed by the blower model number and series, are the recommended spare parts for a normal overhaul. This list includes all bearings, seals, and miscellaneous lock and screws that are not normally reusable after disassembly.

Prices quoted are FCA, Springfield, MO USA. Minimum order \$50.

### **REPAIR KIT 29218**

<u>Item Number</u>	<u>Description</u>	<u>Part Number</u>	<u>Quantity</u>
9	70016	Ball Bearing	4
12	70024	Lip Seal	5
16	70031	Timing Gear Shim	1
24	70069	Gear Key	2
50	32386-22219	Roller Bearing	1
60	70081	Lab Seal	4
70	70260	O-Ring	1
80	29361-035	O-Ring	8

---

The following part is listed for reference only and is not a part of the repair kit:

8	Gear Assembly	70026	1
---	---------------	-------	---

Updated 12-2011 per SAP BOM dp